<b>Work Orde</b> July 13, 2009 12		<b>39</b>									Page 1	
	D3151-1 C			Accept				s	etup Start			=
		Start Qty: 6.00 Req'd Qty: 6.00		i (	Cust Item II Customer:	D:			Stop			
Approvals:	Process Plan: QC:	MF	Date: <u>09-07-1</u>			ite:		R	tun Start Stop			
Sequence ID/ Work Center ID		peration escription		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	_
Draw Nbr	Revisio	on Nbr				. ,				· · · · · · · · · · · · · · · · · · ·		
D3151	Rev C											
Waterjet FLOW CNC Waterje		LOW WATER JET  Memo  1-Cut as per Deburr if ne		0.00  0.00  ev: □Prog Rev:_	<u> </u>			(B	9-8-13	<b>&gt;</b>		
110 QC Quality Control	Q	C2- Inspect parts off n  Memo	nachine FAI/FAIB	0.00 : 0.00				HR (	7-8-13			
120 QC Quality Control	Q	QC8- Inspect parts - sec Memo	ond check	0.00	Jorlos)			(E)	\$		- <del></del>	

A CONTROL OF THE PROPERTY OF T

Work Order ID 50	0	3	89
------------------	---	---	----

C

Page 2

July 13, 2009 12:53:54 PM

Item ID:

D3151-1

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Required Date: 7/15/09

Bracket Flat Pattern

**Start Date:** 

7/15/09

Start Qty: 6.00

Req'd Qty: 6.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

0.00

**SPC**<sup>1</sup>(Y/N):

Date:

Date:

Run

Qty

Start

Stop



Sequence ID/

**Work Center ID** 

130

Small Fab

Small Fab

**Operation** Description

Small Fab

Set Up/

**Run Hours** 

Draw Number Draw Rev.

Plan Code

Accept Qty

Reject Reject Number

Insp. Stamp

Memo

Memo

0.00 Memo

Date: \_\_\_\_\_

Deburr D3151-1□C'sink holes as per Dwg D3151

m/ 09/08/



140

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

150

HandFinish

Hand Finishing

Chemical Conversion Coat per OSI005 4.1

0.00

-> 9/ 09/08/14(V9)

## Work Order ID 50389

July 13, 2009 12:53:54 PM



Page 3

Item ID:

D3151-1

C

**Revision ID:** Item Name:

Bracket Flat Pattern

**Start Date:** 

7/15/09

Start Qty: 6.00

Required Date: 7/15/09

Accept

Setup Start

Stop



**Cust Item ID: Req'd Qty:** 6.00 **Customer:** 

Date:\_\_

Reference:

Approvals:

Process Plan:

Date:

**Tooling:** SPC (Y/N):

Date: Date: Run

Start

Stop



Sequence ID/ Work Center ID

160

Quality Control

Operation Description

QC3- Inspect Part Finish

Memo

Set Up/ **Run Hours** 

0.00

0.00

Draw Number Draw Rev.

Plan Code Qty

Accept

Reject Qty

Reject Number

Insp. Stamp

170

180

Packaging

Packaging

Identify as per dwg & Stock Location

Memo

0.00

0.00

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

09/08/19 H

Quality Control

Page 1

## **Picklist Print**

July 13, 2009 12:53:53 PM

Work Order ID: 50389

Parent Item:

D3151-1RevC

Parent Item Name: Bracket Flat Pattern

Comments:



Start Date: 7/15/09

Required Date: 7/15/09

Start Qty: 6.00

Required Qty: 6.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch		Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
M2024T3S.040		Purchased	No			100	sf	77.9100	0.5432	Q		
		I								(		

2024-T3 .040 sheet

Warehouse	Loc Oty	Loc Code		
Location				
Main Warehouse				
MAT	77.91			
110337	6.4			
111381	4			
111786	67.51		111786	18 48-13



D3065-5DART AEROSPACE LTD	Work Order:	50.389
Description: Doubler Assembly	Part Number:	D3151-1
Inspection Dwg: D3151 Rev: C		Page 1 of 1

	FIR	ST ARTICLE II	NSPECTI	ON CHE	ECKLIST		
		X First Arti	cle	Prot	otype		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Co	mments
Ø0.098	+0.004/-0.001	. 699	×				
Ø0.250	+0.005/-0.001	.358	<b>X</b>				
Ø0.700	+0.008/-0.001	10,	×				
. 4.50	+/-0.030	4,503	<b>*</b>				
2.75	+/-0.030	2,746	<b>)</b> c				
0.688	+/-0.010	383;	<b>/</b> =				
0.344	+/-0.010	345	×				
1.075	+/-0.010	1,076	<b>&gt;</b> 0				
2.150	+/-0.010	2151	<b>X</b>				
3.800	+/-0.010	3.802	<b>&gt;</b>				
1.975	+/-0.010	1,972	<b>&gt;</b>				
0.350	+/-0.010	357	*				
2.050	+/-0.010	2,049	89				
1.375	+/-0.010	1,377	×				
0.350	+/-0.010	350	*				
	_						
						_	
			1.6	·	· · · · · · · · · · · · · · · · · · ·		
Measured by:	B	Audited by:	3,		Prototype Ap	proval:	N/A
Date:	98-B	Date:	<b>ा ७</b> ७	<u>r</u>		Date:	N/A
	•	_					


Rev	Date	Change	Revised by	Approved
Α	08.05.20	New issue	KJ/DD	
				<b>V</b>





DESIG	r RF	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANADA	
CHEC	KED , I _	APPROVED AL	DRAWING NO.	REV. C
	世	#	D3151	SHEET 1 OF 1
DATE			TITLE	SCALE
05.1	2.07		DOUBLER ASSEMBLY	1:4
Α		02.04.23	NEW ISSUE	
В		04.09.08	RE-DESIGN	
С		05.12.07	REVISE NOTES	



## D3151-041 DOUBLER ASSEMBLY REPLACES PREMIER P/N B30-23000-173/-174







SHOP COPY **RETURN TO** 1 GINEERING

**UNCONTROLLED COPY** SUBJECT TO AMENDMENT WITHOUT NOTICE

WORK ORDER NO.50389

mr 09-07-15

## NOTES

- 1) MATERIAL: 2024-T3 SHEET (QQ-A-250/4) 0.040" THICK (REF. DART SPEC. M2024T3S.040)
  2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
  3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.010
  6) IDENTIFY WITH DART P/N D3151-041 USING FINE POINT PERMANENT INK MARKER

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.